

# HORSHAM AVIATION SERVICES

Certificate of Approval No: 1363

**LAST INSP: 10,819.0 = FS**

Date: 15.09.2017

VH- TXB A/C TYPE **C207A** SERIAL NO **207-00713** DATE ..... JOB NO ..... A/F HRS.....F/S HRS

<b>ENG O/H DUE</b> 10,803.1 A/F HRS OR 04.02.2019 (1700/12YR TBO)	<b>PROP O/H</b> 11,726.5 A/F HRS OR .../.../... (2000 TBO)	<b>HEATER HRS</b> NA
<b>PART LIFED COMPONENTS</b>	<b>BRAKE DISC P/N..</b>	<b>MIN DIM 0.327</b>
<b>ALT HISTORY</b> PN 9910592-1, SN A1855310 was installed new @ 10,019.9 AF hrs on 01.12.09		<b>V/PUMP HISTORY</b> AA3216CW SN 01S119 fitted 21.11.2013 @ 10,786.8 A/F hr

ITEM	M/R	AD	REF	AD TITLE	COMPLIANCE	DUE AT/ON	ACTION	CERTIFICATION
1		AD/	CESS207/26A1	BLADDER TYPE FUEL CELLS - INSPECTION	EACH M/R ISSUE	NOW		
2		AD/	AD/2011-10-09	SEAT ADJUSTMENT MECHANISM	EACH M/R ISSUE	NOW		
3		AD/	CESS207/32A2	FORWARD DOOR POST BULKHEAD (REF: SB 93-5) Cessna MOD KIT INSTALLED	500 HOUR REC'	N/A		Terminating action SK207-19 installed
4		AD/	ENG/4A11AppARe	PISTON ENGINE MAINTENANCE	110 HR REC	NOW		
5		AD/	PROP/1A2	OH REQUIREMENTS	2000Hr	11,726.5		
6		AD/	CON/60A4 Rq 1&3	FUEL INJECTION SUPPLY LINES	110 HOUR REC'	NOW		
7		AD/	ELEC/59A1	MAGNETO SWITCH INSP	2000HR REC			NA TCM SWITCH INSTALL
8		AD/	GEN/87	PRIMARY FLIGH CONTROL CABLES	15 YR RECURRING	01.01.2018		ENDORSE MR
9	**	CAO	100.5 C14	TRANSPONDER PERIODIC TESTING	2 YEAR REC'	25.11.2018		
10		CAO	100.5 C3	PITOT STATIC LEAK TEST	2 YEAR REC'	25.11.2018		
11		CAO	100.5 C4	PRESSURE ALTIMETER TEST & ENCODER	2 YEAR REC'	25.11.2018		
12		CAO	100.5 C5	AIRSPEED INDICATOR TEST	4 YEAR REC	25.11.2020		
13		CAO	100.5 C6	FUEL CALIBRATION	4 YEAR REC	25.11.2020		
14		AWB	34-008 ISSUE 1	MAGNETIC COMPASS SWING	3 YEAR REC'	03.04.2019		
15				REPLACE THE NLG DRAG LINK BOLTS PN NAS464P5A42 & AN6-32A	/ 1000 HR	11,777.1		
16		AD/	INST/46R3	STANDBY VAC SYSTEM INSPECTION REQ	12 MTHS REC	NOW		
17		AD/	RAD/50A1	ELT PERIODIC MAINTENANCE	BATTERY LIFE INTERVALS 5Yr	SEP 2019		FUNCTION TEST 15.09.2017
18		AWB	02-048 ISS 5	CESSNA SIDS MANDATE	EA MR	NOW		
19		AWB	26-003#6	FIRE EXTINGUISHANT SYSTEMS	5 YEAR BOTTLE LIFE			NONE INSTALLED

\*\*\*\*\* PTO FOR UPDATED ADS \*\*\*\*\* UPDATED WB 18.09.2017

ITEM	M/R	AD	REF	AD TITLE	COMPLIANCE	DUE AT/ON	ACTION	CERTIFICATION
20				Alternator Inspection (SN A1855310 95A	1000HR REC'	11,802.8		
21				Vac Pump insp (SN 01S119	600 HR INITIAL	11,386.8		
22				500HR MAGNETO INTERNAL INSP	500 HOUR REC'	11,300.8		
23				IFR 100 HOURLY	12MTH / 100 HRS	NOW		
24		AD/	HOSE/2A2	AIRFRAME FLEXIBLE HOSES	6 YEAR REC' Last Renew ed	O.C.		AD Cancelled Vis Inspn 15.09.2017
25		AD/	HOSE/3A6	ENGINE COMPARTMENT FLEXIBLE HOSES	6 YEAR REC' Last Renew ed 19.12.2012	ALL TEFLON		AD Cancelled Vis Inspn 15.09.2017

CESSNA SID OPS CO #s .....

DATE ....., AFHRS .....

AD REVIEW

<b>AIRFRAME</b>	21.11.13 NO NEW ONES LAST ONE CESS207/2012-10-52
<b>ENGINE</b>	21.11.2013 NO NE WONES LAST ONE CON/2012-10-13. AD/CON/2014-05-29 Superior Airparts cylinders was checked and found NA, to the 6 x TCM cylinder installed
<b>PROPELLER</b>	21.11.2013 NO NEW AD/PROP OR PMC
<b>GENERAL / EQUIPMENT</b>	AD/GEN/86 Darwin inspection & testing service ultrasonic inspection is NA by work status. AD/RES/2013-0020R4 equipment & furnishings & safety belts / torso restraint system inspection / replacement was checked & found NA to the installed non dynamic seat belt assemblies. RES/2014-0279 Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Identification / Replacement was checked & found NA by belt manufacture
<b>15.09.2017</b>	<b>ENG</b> - AD/CON/2016-16-12 ECI cylinder head to barrel separations & cracked / leaking aluminum cylinder inspection / replacement was checked & found NA by cylinder MFG & PN. AD/CON/2016-21-04 Engine oil cooler cross fitting assembly replacement was checked & found NA by engine model. <b>GEN</b> - AD/INST/2017-04-06 United Instruments Inc 5934 series altimeters replacement was checked and found NA to the pilots United altimeter PN 5934PM-1, SN 464102 by SN & the co-pilot's altimeter by MFG (a instruments & Flight research PN IFR46-20M SN M4477 is fitted to the co-pilot's side).